

M 121-52

FILED

Date: 2-16-95 By: JS

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: \_\_\_\_\_

OREGON CORNER RESTORATION FORM

Section 34 Township 26S Range 3W

County Douglas Date Feb. 3, '95

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

SE 1/16 Corner, Sec. 34

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals/Surveys, etc.

Survey by Mehind, 1973, County Surveyor Map File  
M51-34

Monument(s) & Accessories Found: (Condition and Source)

Found 5/8 inch Iron Rod at Fence Corner,  
fence bears North & West, & from which iron rod a:  
22" Cedar BT Stump, scribes visible, bears  
N49 1/2° W (Record N53 3/4° W), 122.5 feet.

Monument Detail

Sketch

N/A

Monument Set (Procedures and Description)

N/A

New Accessories

8" D. Fir BT, I scribed "SE 1/16 S34 BT" bears  
N57°W, 79.3 feet.

8" D. Fir BT, I scribed "SE 1/16 S34 BT" bears  
N25° E, 81.4 feet.

Location & Comments

None

Compass Declination 21°E

Firm/Agency Shaner

Engineering, Inc.

Address P.O. Box 1430

Roseburg, Oregon 97470

Party Chief B. Shaner

Notes \_\_\_\_\_

Witness Jack Wright

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Bruce A. Shaner  
OREGON  
OCT. 4, 1957  
BRUCE A. SHANER  
430

Expires June 30, '96