

* See 2006 BLM Resurvey M119-52
Pg 22521, for New
Corner position

FILED

Date: 3/9/95 By: AP
This survey consists of:
Map: M.119-52
Narrative: _____
Corner Ref: C.S. 63/161

OREGON CORNER RESTORATION FORM

Section 30 Township 30S Range 3W

County Douglas Date Feb. 28, '95

DOUGLAS COUNTY
SURVEYOR

Corner Designation

S 1/16
530 • 529

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____


None.

Monument(s) & Accessories Found: (Condition and Source)

N/A

Monument Detail

Sketch



* Monument Set (Procedures and Description)

I set a 3" Brass Cap on a 2 1/2" x 30" Iron Pipe and from which a:

New Accessories

No live trees within reasonable distance due to the disastrous Bland Mountain fire, so I set 6 foot steel fence posts for bearing objects as follows:
North, 12 feet; South, 12 feet; West, 12 feet.

Location & Comments

None.

Compass Declination 20°E

Firm/Agency Shaner

Engineering, Inc.

Address P.O. Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness David Snyder

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner

OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Expires June 30, 1996

C.S. File No. 63/161-15