

FILED

Date: 7-28-95 By: JP
This survey consists of:
Map: M 122-23
Narrative: _____
Corner Rpt: C.S. 63/161-35

OREGON CORNER RESTORATION FORM

Section 25 Township 31S Range 6W

County Douglas Date July 26, 1995

Corner Designation

DOUGLAS COUNTY
SURVEYOR

1/4 525

536

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Bruce Shaner, 1981.

Monument(s) & Accessories Found: (Condition and Source)

Found same as described by Shaner in 1981.

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Set 6 foot steel post, North, 12 feet.

Location & Comments

Placed Tag on
USBLM Road.
N 30° W, 120° feet

Compass Declination 18°

Firm/Agency Shaner

Engineering

Address P.O. Box 1430

Roseburg, Oregon 97470

Party Chief B. Shaner

Notes " "

Witness David Snyder

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A Shaner

OREGON
JCT 4, 1957
BRUCE A. SHANER
430

Reviews 6-30-96