

GOVERNMENT CORNER RESTORATION FORM

Township 27S Range 6W Sec. 16 County DOUGLAS MAR 8 1990

State OR Date 3/1/90 No. _____ COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

S17/S16
S20/S21

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #78

Monument(s) Found: (Condition and Source)

A DCSO 2 1/2" DIA. BRASS CAP ON
A 1/4" O.D. IRON PIPE WHICH
PROTRUDES 18" ABOVE GROUND.

A 1/2" O.D. IRON PIPE, PROTRUDES
11" ABOVE GROUND BEARS S62°E,
0.7 FT FROM DCSO BC/IP.

COUNTY SURVEYOR'S OFFICE

T27S R6W

S17/S16
S20/S21

1960

Accessories Found:

BEARING'S AND DISTANCES TAKEN TO DCSO BC/IP
14" NOW ROTTED MADRONE STUMP OF INDETERMINATE SIZE WITH
A CLUSTER OF NEW MADRONES GROWING FROM STUMP ROOTS, BEARS
BEARS N80 1/2°E, 158.4 FT (ORIG. REC N88 1/4°E, 158.4 FT.
REN #78 N83°E) POSSIBLE ORIG. BT

9" NOW 20" DIA. B. OAK WITH A PREVIOUSLY OPENED BLAZE,
NO SCRIBING VISIBLE, BEARS S47 1/2°E, 81.6 FT (ORIG. REC
S45 1/4°E, 86.5 REN #78 S45 1/4°E, 82.5) ORIG. BT

6" NOW 21" DIA. W. OAK WITH A FULLY HEALED SINGLE BLAZE,
BEARS N41 1/2°W, 55.4 FT (AGREES WITH REC.) ORIG. BT

20" NOW 28" DIA. W. OAK WITH A PREVIOUSLY OPENED BLAZE, NO SCRIBING
VISIBLE, BEARS S60 1/2°W, 169.0 (REC S63°W, 169.0 FT) ORIG. BT

5" NOW 6" DIA. W. OAK WITH A FULLY HEALED DOUBLE BLAZE,
BEARS S66°E, 42.4 FT (AGREES WITH REC) REN #78

6" NOW 7" DIA. W. OAK WITH A FULLY HEALED DOUBLE BLAZE,
BEARS N39°E, 50.0 FT (AGREES WITH REC) REN #78

10" NOW 10" DIA. W. OAK WITH A FULLY HEALED DOUBLE BLAZE,
BEARS S69°W, 121.9 FT (REC S69°W, 122.8 FT) REN #78

#189 X

