

## GOVERNMENT CORNER RESTORATION FORM

FILED

Township 255 Range 2W Sec. 26 County DOUGLASState OR Date 8/16/90 No. \_\_\_\_\_

AUG 21 1990

Corner Designation

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

522	523
527	526

Condition Report Only

Not Found

 Renewed Unrecorded Surveyed In Referenced Out

MONUMENT DETAIL

Previous Renewals #36, 1978 BLM SURVEY

Monument(s) Found: (Condition and Source)

A 2 1/2" DIA DCSO BRASS CAP ON A  
1 1/2" O.D. IRON PIPE, PROTRUDING  
15" ABOVE GROUND. (REN #36)

DCSO BR/1P IS SURROUNDED BY  
LOOSE STONES NO UNNATURAL MARKS  
FOUND.

COUNTY SURVEYORS OFFICE

T 255

522	523
527	526

R 2W

1958

Accessories Found:

60" NW 48" DIA 5 FT HIGH PINE STUMP WITH A HEALED BLAZE  
BEARS N37°E, 38.9 FT (AGREES WITH ORIG. RECORD) ORIG. BT

30" NW 26" DIA, 9 FT HIGH D. FIR STUMP WITH A HEALED DOUBLE  
BLAZE, BEARS S25°E, 21.1 FT (AGREES WITH ORIG. RECORD) ORIG. BT

26" NW 39" DIA, 2 FT TALL D. FIR STUMP WITH A HEALED LOWER BLAZE  
BEARS N44°W, 37.4 FT (REC N44°W, 38.9) ORIG. BT

18" ~~BLAZE~~ SOUTHWEST BT IS GONE

4" NW 2" DIA, HEMLOCK WITH A FULLY HEALED DOUBLE BLAZE  
BEARS S80Y2°W, 22.3 FT (REC S80Y2°W 1278 BLM) AND AGREES  
WITH REN #36, DISTANCE OF 22.3 FT) REN #36

7" NW 7" DIA DOWN AND ONE OF POSITION HEMLOCK WITH SCRIBING  
VISIBLE ON AN UNHEALED BLAZE " T255 R2W S26 1BT " A BROKEN  
PORTION OF STUMP REMAINS WHICH BEARS S53°E, 10.6 FT  
(AGREES WITH RECORD) 1278 BLM.

#125 ✓

C.S. File No. 64/1059 C

