

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 29S Range 5W Sec. 31 County DOUGLAS

State OR Date 5/13/91 No. \_\_\_\_\_

MAY 28 1991

Corner Designation

1/4S31|S32

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #46 #131 #199 M1-35

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A 2 1/2" DIA. DCSO BRASS CAP ON A  
1" I.D. IRON PIPE PROTRUDES 4" ABOVE  
GROUND.

A STONE WHICH TOP MEASURES 10"  
BY 6" PROTRUDES 4" ABOVE GROUND  
"1/4" IS MARKED ON SOUTH SIDE.  
BEARS NORTH 6" FROM BC/IP  
REN #46?

A 1" I.D. IRON PIPE IS FOUND ALONG  
SOUTH EDGE OF BC/IP PROTRUDING  
4" ABOVE GROUND. M1-35

DOUGLAS COUNTY SURVEYORS

T 29S R5W

1/4 S31 | S32

1979

Accessories Found:

18" NOW 38" DIA. B. OAK WITH A FULLY HEALED SINGLE BLAZE,  
BEARS S20°E, 15.2 FT (REC. S15°E, 15.2 FT) ORIG. BT

ORIG. NW BT NOW GONE

8" NOW 12" DIA. W. OAK WITH A FULLY HEALED DOUBLE BLAZE,  
BEARS N59°W, 57.5 FT (AGREES WITH REC) REN #131

28" NOW 30" DIA. B. OAK WITH AN UNHEALED DOUBLE BLAZE, SCRIBING  
VISIBLE "1/4S31CS BT", BEARS S31°W, 54.1 FT. (AGREES WITH REC.)  
REN #199

#231 X

U.S. File No. 64/15-6 c

