

Monument Set (Procedure and Description) NONE

ACCESSORIES FD:

26" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE AND A "W" NAIL DRIVEN THROUGH THE CENTER OF A 3" DIA. BRONZE DISK MARKED "REG. ENGINEER NO. 2149" BEARS N 54° W, 12.2 FT (AGREES WITH 1958 BLM). WEY CO.

BT'S FROM 1958 BLM

12" NOW 31" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE, BEARS N 77 1/2° E, 73.9 FT (REC N 79 3/4° E, 73.9 FT) 1958 BLM

16" NOW 24" DIA. TIPPED OUT D. FIR WITH A FULLY HEALED SINGLE BLAZE, ROOT HOLE BEARS S 74 1/4° E, 44.9 FT (AGREES WITH REC) 1958 BLM


N/A

New Accessories FD:

7" NOW 12" DIA. 7' HIGH CEDAR SNAG WITH AN OPEN BLAZE, SCRIBING VISIBLE "T 22 S R 4 W", BEARS N 79° W 38.6 FT (REC N 80° W 38.6 FT) 1958 BLM

12" FIR BEARING N 27° W IN 1958 BLM IS GONE.

Sketch of Monument, Accessories, and General Area



Location & Comments

Comp. Declin. 18° E
 Agency D L S O
 Party Chief RANDALL W SMITH
 Notekeeper Randall W Smith
 Witnesses STEPHEN J FLANSE

Address

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Randall W Smith

OREGON
 JULY 25, 1990
 RANDALL W. SMITH
 2469