

GOVERNMENT CORNER RESTORATION FORM

Township 20S Range 4W Sec. 31 County DOUGLAS DEC 5 1991

State OR Date 11/7/91 No. _____

UNITY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

S36 | S31

S1 | S6

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #119, 1968 BLM

Monument(s) Found: (Condition and Source)

A 2 1/2" DIA. DCSSO BRASS CAP
ON A 1/4" O.D. IRON PIPE, PROTRUDING
14" ABOVE GROUND. REN #119

A 3/4" I.D. IRON PIPE IS FOUND
ALONG EAST EDGE OF BC/IP. (SOURCE UNKNOWN)

A STONE MEASURED 20" X 9" X 5"
MARKED "RSW S36" IS FOUND
LOOSE ALONG NE EDGE OF BC/IP
(SOURCE UNKNOWN)

DOUG. CO. SURVEYORS
 T20S R4W
 S36 | S31

 S1 | S6
 R5W T21S
 BLM 1968
 1965

MONUMENT DETAIL

Accessories Found:

8" NOW 14" DIA. ROTTED D. FIR STUMP, NO BLAZES OR SCRIBING
VISIBLE BEARS N 50° W 5.3 FT (AGREES WITH REC.) ORIG. BT

8" NOW 17" DIA. ROTTED D. FIR STUMP*, NO BLAZES OR SCRIBING
VISIBLE BEARS N 72° W 7.0 FT (AGREES WITH BLM REC) ORIG. BT

7" NOW ROTTED D. FIR STUMP OF INDETERMINATE SIZE, NO BLAZES
OR SCRIBING VISIBLE, BEARS S 15° W, 5.9 FT. (AGREES WITH REC) ORIG. BT

7" NOW 2" DIA. 30' HIGH D. FIR SNAG WITH A FULLY HEALED DOUBLE BLAZE
BEARS S 44 1/2° W, 4.5 FT (AGREES WITH BLM BRG. AND REN 119 DIST.) REN 119

8" NOW 12" DIA. 7 FT. HIGH D. FIR STUMP WITH A FULLY HEALED DOUBLE BLAZE
BEARS N 4° W, 7.0 FT (AGREES WITH REN #119) REN 119

7" NOW 10" DIA. D. FIR WITH A FULLY HEALED DOUBLE BLAZE, BEARS
S 89° E, 17.2 FT (REC EAST IN REN 119 AND N 85 1/2° E BY BLM,
DIST 17.3 FT AGREES) REN 119

8" NOW 9" DIA. D. FIR WITH A FULLY HEALED DOUBLE BLAZE,
BEARS S 23° E, 23.1 FT (REC S 21° E REN 119 AND S 20 1/2° E
BY BLM DIST 23.2 AGREES WITH REC) REN 119

160 T21-4
177A F.21-5

