

GOVERNMENT CORNER RESTORATION FORM

FILED *JK*

Township 27S Range 6W Sec. 20

County DOUGLAS

JUN 8 1993

State OR

Date 5-10-93

No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

$\frac{1}{4}$ S 20 | S 21

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1961 BYRON

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A 1 1/2" O.D.
IRON PIPE PROTRUDING 18" ABOVE
GROUND. (1961 BYRON)

COUNTY SURVEYOR'S OFFICE

T 27S R 6W

$\frac{1}{4}$ S 20 | S 21

1961

Accessories Found:

10" NOW 11" DIA. B. OAK WITH A FULLY HEALED DOUBLE BLAZE,
BEARS N 32° W 18.3 FT (AGREES WITH REC) 1961 BYRON

12" NOW 15" DIA. W. OAK WITH A FULLY HEALED DOUBLE BLAZE,
BEARS N 16 1/2° E, 28.1 FT (AGREES WITH REC)

15" NOW 22" DIA DOWN A ROTTED OAK, NO SCRIBING OR
BLAZES VISIBLE, ROOT HOLE BEARS N 43 1/2° E, 72.6 FT
(AGREES WITH REC) ORIG.

20" NOW 20" DIA 2 FT HIGH ROTTED OAK STUMP NO
SCRIBING OR BLAZES VISIBLE, BEARS S 83° W, 26.8 FT
(REC FROM 1961 REN S 83° W 24.4 FT) ORIG?

300340

C

