

GOVERNMENT CORNER RESTORATION FORM

FILED

Handwritten initials

Township 27S Range 6W Sec. 18 County DOUGLAS

MAY 12 1993

State OR Date 5-4-93 No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

WC
S13/S18
S24/S19

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals 1960 BYRON

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON A 1 1/2" O.D. IRON PIPE, PROTRUDING 12" ABOVE GROUND. (1960 BYRON)

COUNTY SURVEYORS OFFICE

T 27 S

R S13/S18 R
7 6
W S24/S19 W

COR. 5'
EAST
1960

Accessories Found:

NO ORIG. BT'S FOUND

BT'S FROM 1960 BYRON RENEWAL

7" NOW 11" DIA, W. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS N 22° W, 40.9 FT (REC N 23° W, 40.9 FT)

18" NOW 18" DIA, 4 FT HIGH D. FIR SNAG WITH A PARTIALLY HEALED UPPER BLAZE, SCRIBING VISIBLE "W WC S24CS", LOWER BLAZE IS HEALED. BEARS S 62° W, 46.5' (AGREES WITH REC.)

11" NOW 15" DIA, W. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS S 47° E, 62.3 FT (REC S 48 1/2° E, 62.3 FT)

11" NOW 18" DIA W. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS N 6° E, 32.3 FT (REC. N 4 1/2° E, 32.3 FT)

T 27-6 ✓
100400 .002

T 27-7 ✓
700400 .012

C.S. File No. 69/43-B

