

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 22S Range 5W Sec. 26 County DOUGLAS

State OR Date 4-27-93 No. _____

MAY 12 1993

Corner Designation

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

DLC
43

Previous Renewals 1971 BYRON

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A 1 1/2" O.D. IRON PIPE, PROTRUDING 13" ABOVE GROUND. (1971 BYRON)

MONUMENT DETAIL

COUNTY SURVEYORS OFFICE

T27S R5W
NW COR.

D.L.C.
43

1971

Accessories Found:

ORIG 17" B.OAK NOW DEPRESSION IN GROUND, NO REMAINS VISIBLE, BEARING AND DISTANCE OF ORIG. REC. (S68°E, 85.8 FT) ORIG BT POSITION

18" NOW 18" DIA. DOWN OAK WITH A FULLY HEALED DOUBLE BLAZE, ROOT HOLE BEARS N89°E, 62.7 FT (AGREES WITH REC) 1971 BYRON

30" NOW 31" DIA B.OAK WITH A FULLY HEALED SINGLE BLAZE, BEARS N45°W, 89.4 FT (AGREES WITH REC) 1971 BYRON

