

Township 275 Range 4W Sec. 30 County DOUGLAS

State OR Date 4-27-93 No. \_\_\_\_\_

MAY 12 1993

Corner Designation

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

1/4 S25 | S30

Previous Renewals 1959 BYRON

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON 1 1/2" O.D. IRON PIPE, PROTRUDING 12" ABOVE GROUND (1959 BYRON)

COUNTY SURVEYORS OFFICE

R            1/4            R  
 S            S | S            4  
 W            25 | 30            W  
  
 T 275  
 1959

Accessories Found:

12" NOW 26" DIA 3' HIGH B. OAK STUMP, POSSIBLE HEALED LOWER BLAZE, FALLEN OAK TREE ALONG WEST SIDE, REOPENED PREVIOUSLY OPENED BLAZE, FIND BLAZE, AXE MARKS AND ILLEGIBLE SCRIBING. STUMP BEARS S 20° W, 79.8 FT (REC S 20° W, 82.5 FT) AREA OF CORNER IS ON A STEEP NORTH SLOPE, WHICH MAY ACCOUNT FOR DISTANCE PROBLEM. ORIG. BT

11" NOW 22" DIA. D. FIR WITH A FULLY HEALED DOUBLE BLAZE, BEARS S 72° W, 24.0 FT (REC. S 72° W, 24.7 FT.) 1959 BYRON

14" NOW 18" DIA 1 1/2' HIGH D. FIR STUMP, I OPENED A LOWER BLAZE AND FIND SCRIBE MARKS "BT", STUMP BEARS N 81° E, 18.7 FT. (REC N 21° E, 12.5 FT.) 1959 BYRON

700240 T27-4.001 ✓  
700240 T27-5.001 ✓

C.S. File No. 6A/43520

