

GOVERNMENT CORNER RESTORATION FORM

FILED JP

Township 27S Range 6W Sec. 29 County DOUGLAS

State OR Date 5-12-93 No. _____

JUN 10 1993

Corner Designation

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

1/4 S 29
S 32

MONUMENT DETAIL

Previous Renewals 1961 BYRON

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAP ON A 1 1/2" O.D. IRON
PIPE, PROTRUDING 12" ABOVE GROUND
(1961 BYRON)

COUNTY SURVEYORS OFFICE

T 27S R 6W

1/4 S 29
S 32

1961

Accessories Found:

15" NOW 26" DIA. B. OAK WITH A FULLY HEALED BLAZE,
BEARS S 65° W 48.2 FT (REC S 66 1/2° W 48.2 FT)
ORIG BT

14" NOW 14" W. OAK RECORDED IN 1961 RENEWAL
AS BEARING N 64 1/2° W 64.7 FT, WAS OPEN IN TWO PLACES
NO BLAZING OR SCRIBING FOUND. THE ABOVE BEARING AND
DISTANCE IS SAME AS ORIG. 6" NW BT. WE FIND
BEARING AND DISTANCE TO BE N 65 1/2° W, 64.0 FT ORIG BT?

14" NOW 18" DIA. MDOBANK WITH A FULLY HEALED DOUBLE
BLAZE, BEARS S 71° W, 48.7 FT (REC S 73° W 48.7 FT)
1961 BYRON

11" NOW 16" DIA B. OAK WITH A FULLY HEALED DOUBLE
BLAZE, BEARS N 57 1/2° W, 48.0 FT (REC N 56 1/2° W, 48.0 FT)
1961 BYRON

Monument Set (Procedure and Description)

Monument Detail

NONE

N/A

New Accessories

14" DIA W. OAK THAT WE OPENED IN TWO PLACES LOOKING FOR SCRIBING (SEE FRONT) BLAZED ABOVE AND BELOW AXED OPENINGS AND SCRIBED "Y4S29CS BT" BEARS N65 1/2°W, 64.0 FT

17" DIA D. FIR DOUBLE BLAZED AND SCRIBED "Y9S52CS BT" BEARS S 12 1/2°E, 7.2 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

NORTH - SOUTH FENCE LINE IS 40 FT WEST OF CORNER

Comp. Declin. 18°E
Agency DCSO
Party Chief RANDALL W SMITH
Notekeeper *Carroll W Smith*
Witnesses STEPHEN J FLAUS

Address

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Randall W Smith
EXPIRES 12-31-94

OREGON
JULY 25, 1990
RANDALL W. SMITH
2489

