

GOVERNMENT CORNER RESTORATION FORM

FILED JP

Township 27S Range 6W Sec. 35 County DOUGLAS

AUG 25 1993

State OR Date 6-23-93 No. \_\_\_\_\_

Corner Designation

COUNTY SURVEYOR  
DOUGLAS COUNTY, OR

DLC  
55

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1940 EPPSTEIN, 1960 BYRON, 1964 GODFREY

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A 1 1/2" O.D.  
IRON PIPE, PROTRUDES 12" ABOVE  
GROUND. A LOOSE MOUND OF STONES IS  
AROUND BASE OF PIPE.

COUNTY SURVEYORS OFFICE

T27S R6W

4" X 4" OAK STAKE NOT FOUND.

N.W.  
COR.  
D.L.C.  
55  
1960

Accessories Found:

6" NW 15" DIA. W. OAK WITH A FULLY HEALED DOUBLE BLAZE  
BEARS N21 1/2° W, 88.1 FT (REC N20 1/2° W, 87.5 FT) 1960 BYRON

24" NW 48" DIA. DEAD W. OAK WITH A FULLY HEALED SINGLE BLAZE,  
BEARS N1° E, 209.2 FT (AGREES WITH REC) 1940 EPPSTEIN

24" NW 29" DIA. W. OAK WITH A FULLY HEALED SINGLE BLAZE,  
BEARS N10 1/4° E, 236.5 (REC N9 1/4° E, 231.7 FT IN 1960 AND  
N 9 1/4° E, 237.2 IN 1940. BOTH RENEWALS CREDIT  
G.G. STEWART WITH SCRIBING TREE, 1940 REN SAYS TREE IS  
ROTTING, THIS TREE LOOKED HEALTHY, I'AM UNCERTAIN OF THE  
SOURCE OF THIS TREE).

