

GOVERNMENT CORNER RESTORATION FORM

FILED JP

Township 28S Range 7W Sec. 28 County DOUGLAS

OCT 17 1993

State OR Date 10-12-93 No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

SE COR
DLC 54

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals 1922, 1957, AND 1976 DCSO

Monument(s) Found: (Condition and Source)

2 1/2" DCSO BRASS CAP ON A 1 1/2" O.D
IRON PIPE PROTRUDING 6"
ABOVE GROUND (1976 DCSO)

3/4" I.D. IRON PIPE PROTRUDING
5" ABOVE GROUND IS FOUND ALONG
EASTERLY EDGE OF DCSO BC/1P
(1922 DCSO)

DOUGLAS CO. SURVEYOR

DLC 54

S.E. COR.

T28S R7W

1976

Accessories Found:

10" NOW 23" DIA. 18 FT HIGH D.FIR SNAG WITH A HEALED
PREVIOUSLY OPENED BLAZE, BEARS N20°W, 24.4 FT
CAGREES WITH REC.) (OBT)

24" NOW 34" DIA 5 FT HIGH D.FIR STUMP WITH A FULLY
HEALED SINGLE BLAZE, BEARS N76°W, 9.3 FT
CAGREES WITH REC.) (1957 DCSO)

6" NOW 5 FT HIGH ROTTED MAPLE STUMP OF INDETERMINABLE
SIZE, NO BLAZES OR SCRIBING VISIBLE, BEARS S46°E, 12.4 FT
CAGREES WITH REC.) (1922 DCSO) NOTE STUMP IS SPROUTING
NEW GROWTH,

6" NOW 14" DIA D.FIR WITH A FULLY HEALED DOUBLE
BLAZE BEARS N12 1/2°E, 15.1 FT (REC N 2 1/2°E 15.1 FT)
1976 DCSO

2" NOW 15" DIA. D.FIR WITH A FULLY HEALED DOUBLE
BLAZE, BEARS S35 1/2°E, 33.5 FT CAGREES WITH REC.)
1976 DCSO

054060

