

GOVERNMENT CORNER RESTORATION FORM

Township 24S Range 4N Sec. 34 County DOUGLAS

OCT 27 1993

State OR Date 9-20-93 No. _____

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

1/4 S34 | S35

ERRINBOUS 1972 BLM

Previous Renewals 1985 BLM

Monument(s) Found: (Condition and Source)

A 3 1/4" BLM BRASS CAP ON A
2 1/2" O.D. IRON PIPE, PROTRUDED
3" ABOVE GROUND 'E' SET AT
A POSITION AS DETERMINED
IN 1985 BLM SURVEY)

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

MONUMENT DETAIL

U.S. DEPT. OF THE INTERIOR
T 24 S R 4 W

1/4

S34 | S35

1985

1972

BUR. OF LAND MANAGEMENT

Accessories Found:

32" NOW 32" DIA. 2 FT HIGH D. FIR STUMP WITH PARTIALLY
HEALED LOWER BLAZE NO SCRIBING VISIBLE, BEARS N76°W,
33.7 FT. (AGREES WITH REC) 1985 BLM

14" NOW 15" DIA ASH WITH A PARTIALLY HEALED SINGLE BLAZE
SCRIBING VISIBLE " 1/4 S35 BT" BEARS N61°E, 43.2 FT
(AGREES WITH REC) 1985 BLM

