

GOVERNMENT CORNER RESTORATION FORM

Date: 9/28/95 By: Bc
This survey consists of:

Township 25S Range 2W Sec. 7 County DOUGLAS
State OR Date 4-4-95 No. _____

Map: _____
Narrative: _____
Corner Rpt: 64/63-5

Corner Designation

DOUGLAS COUNTY
SURVEYOR

$\frac{1}{4} \frac{S7}{S18}$

- Condition Report Only
- Not Found
- Recorded
- Surveyed In
- Referenced

MONUMENT DETAIL

Previous Renewals 1962 BLM

Monument(s) Found: (Condition and Source)
3/4" DIA. BLM BRASS CAP ON A
2 1/2" O.D. IRON PIPE. IS FLUSH
WITH TOP OF A 2' DIA. MOUND
OF STONE. (1962 BLM)

ONE OF THE STONE ALONG
NORTH EDGE OF BC/IP IS
FIRMLY SET VERTICALLY WITH
EVIDENCE OF MARKS ON NORTH
FACE ITS TOP MEASURES
6" X 6". (ORIG. STONE) WE
DID NOT DISTURB TO MEASURE
OR CHECK MARKS.

U.S. DEPT. OF THE INTERIOR

$\frac{1}{4} \frac{S7}{S18}$

1962
BUR. OF LAND MANAGEMENT

Accessories Found:

14" NOW 28" DIA. 7 FT HIGH ROTTING HEMLOCK STUMP
SHOWS EVIDENCE OF AXE MARKS AND HEALED BLAZE.
BEARS S13°W, 40.2 FT (REC S16°W, 40.9 FT) OBT.

15" NOW 16" DIA. 6 FT HIGH HEMLOCK STUMP WITH
A FULLY HEALED SINGLE BLAZE BEARS N50°W 50.1 FT
(REC N50°W, 51.5 FT) 1962 BLM (NOTE STUMP
IT HAS A GALVANIZED METAL CAP ON TOP)

