

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 28S Range 2W Sec. 5

County DOUGLAS

Date 12/19/95 By BC
This survey consists of _____

State OR

Date 10-23-95

No. _____

Map: _____

Narrative: _____

Corner Rpt: CS 64/64-6

Corner Designation

1/4 S6 | S5

- Conditional Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals #61 #120

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON AN
IRON PIPE 6" BELOW WITH A 2 1/2"
DIAMETER MOND OF STONE ON TOP
(REN #120)

ALL EVIDENCE OF MONUMENT AND BT'S FROM
REN #61 NOW GONE FALLS
IN CAT ROAD.

T 28S R2W
 1/4
 S6 | S5
 RLS 1654
 1980

Accessories Found:

14" NOW 16" DIA. D. FIR WITH PARTIALLY HEALED
BURNT DOUBLE BLAZE, ILLEGIBLE SCRIBING VISIBLE,
BEARS S42 1/2° W, 25.2 FT (REC. S35° W, 25.2 FT)
(REN #120)

10" NOW 10" DIA 3 FT HIGH MADRONE STUMP WITH A
PARTIALLY HEALED DOUBLE BLAZE, SCRIBING
VISIBLE "1/4 S5 BT" AND 1 1/4" DIA. BRASS WASHER
MARKED "RLS 1005" ATTACHED TO LOWER BLAZE,
BEARS S65 1/2° E, 26.0 FT (REC S64° E, 26.0 FT)
(REN #120)

✓ #132

