

GOVERNMENT CORNER RESTORATION FORM

Date: 8-1-96 By: AC

This survey consists of:

Township 31S Range 6W Sec. 22 County DOUGLAS Map: _____

State OR Date 7-15-96 No. _____ Narrative: _____

Corner Rpt: CS 64/69-14

Corner Designation

1/4 522 | 523

DOUGLAS COUNTY

SIHVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1980 BLM

Monument(s) Found: (Condition and Source)

3/4" DIA BRASS CAP ON A 2 1/2" O.D.
IRON PIPE PROTRUDES 5" ABOVE GROUND.
1980 BLM

U.S. DEPT. OF THE INTERIOR
T31S R6W

1/4

522 | 523

1980

BUR. OF LAND MANAGEMENT

Accessories Found:

6" NOW 11" DIA. D.FIR WITH A FULLY HEALED SINGLE
BLAZE BEARS S88°E, 25.7 (REC / S88°E, 26.4 FT
DIST IS A SLOPE MEASUREMENT) 1980 BLM

10" NOW 11" DIA. D.FIR WITH A FULLY HEALED SINGLE
BLAZE BEARS N55 1/2°W 43.5 FT (REC N55 1/2°W, 44.2 FT,
DIST IS A SLOPE MEASUREMENT) 1980 BLM

