

GOVERNMENT CORNER RESTORATION FORM

Date: 8-8-97 By: AC

This survey consists of:

Township 255 Range 5W Sec. 15 County DOUGLAS Map: _____

State OK Date 7-30-97 No. _____ Narrative _____

Corner Ref. CS 6471-27

Corner Designation _____

$$\begin{array}{r} 515 \\ \hline 1/4 \ 522 \end{array}$$

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1973 DCSO

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAPON
1 1/2" DIA. IRON PIPE PROTRUDING
11" ABOVE GROUND. 1973

COUNTY SURVEYORS OFFICE

T 255 R 5W

$$\begin{array}{r} 515 \\ \hline 1/4 \ 522 \\ 1973 \end{array}$$

Accessories Found:

BENT 5/8" IR. PLUMB POSITION BEARS
S70E 21.6 FT (AGREES WITH REC.) 1973

SE CORNER OF CONCRETE FLOOR TO PUMP
HOUSE BEARS N 89°W 45.9 FT (AGREES WITH REC.)
1973

