

GOVERNMENT CORNER RESTORATION FORM

Date: 7/25/97 By: PRC
This survey consists of:

Township 28S Range 7W Sec. 25 County DOUGLAS
State OR Date: 7-21-97 No. _____
Corner Rpt: CS 64/75-29

Corner Designation

526 | 525

535 | 536

- DOUGLAS COUNTY SURVEYOR**
- Condition Report Only
 - Not Found
 - Renewed
 - Unrecorded
 - Surveyed In
 - Referenced Out

Previous Renewals 1958 DCSO, 1997 SHANER

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A 1 1/2" DIA IRON PIPE PROTRUDING 13" ABOVE GROUND. BC/IP IS BADLY BENT WITH TOP BEING NW 1/4 OF PUMP

MONUMENT DETAIL

DOUGLAS COUNTY SURVEYORS
T28S - R7W

526 | 525

535 | 536

1958
OFFICE

Accessories Found:

FOUND AS NOTED IN 1997 SHANER RENEWAL

