

GOVERNMENT CORNER RESTORATION FORM

Date: 11/13/97 By: PBC

Township 25S Range 5W Sec. 33 County DOUGLAS Map: _____

This survey consists of:

State OREGON Date 10/23/97 No. _____

Narrative: _____

Corner Rpt: CS 64/78-24

Corner Designation

1/4
33 | 34

DOUGLAS COUNTY
SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals GODFREY, 1959

Monument(s) Found: (Condition and Source)

A 2 1/2 INCH DIAMETER BRASS CAP
(MARKED AS AT RIGHT) ON A 1 1/2 INCH O.D.
IRON PIPE FIRMLY SET AND PROTRUDING
APPROXIMATELY 12 INCHES ABOVE GROUND

COUNTY SURVEYORS OFFICE

25S 5W
S33 | S34

1/4

1959

Accessories Found:

AN ORIGINAL 30" DIA. PINE NOW ROTTEN AND BROKEN APPROXIMATELY
2 1/2 FOOT TALL AND 24 INCH DIAMETER PINE STUMP WITH NO SCRIBE MARKS
FOUND BEARS S77°W, 19± FEET (AS PER RECORD)

REMAINS OF TWO BEARING TREES FROM 1959 RENEWAL FOUND
A 9" R. FIR NOW A 12 INCH DBH, 35 FOOT TALL FIR SNAG WITH A
FULLY HEALED DOUBLE BLAZE BEARS N85°E, 26± FEET DISTANT (AS
PER RECORD)

A 22" R. FIR NOW A 23 INCH DIAMETER 18 INCH TALL ROTTEN
FIR STUMP WITH NO SCRIBING OR BLAZE MARKS REMAINING BEARS
N83°W, 30± FEET DISTANT (AS PER RECORD)

