

GOVERNMENT CORNER RESTORATION FORM

Date: 12-9-97 By: PC

Township 27S Range 1W Sec. 21

County DOUGLAS This survey consists of:

State OK Date 12-3-97

No. _____ Narrative: _____

Corner Designation

Corner Rpt CS 64/78-33

S21/S22
S28/S27

DOUGLAS COUNTY

Condition SURVEYOR only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals #118 1970 DCSO

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAP ON A 1 1/2" O.D.
IRON PIPE PROTRUDES 10"
ABOVE A MOUND OF STONE.
ORIG. STONE NOT SEEN.

COUNTY SURVEYORS OFFICE
T27S R1W

S21/S22

S28/S27

1970

Accessories Found:

14" NOW 35" DIA D.I.F.I.R WITH A FULLY HEALED SINGLE
BLAZE, BEARS N 67° E 42.0 FT (REN. REC.
N 67° E, 43.6 FT) OBT

ORIG SE BT NEARLY GONE, BURNT REMAINS
BEARS S 48° E 64.0 FT (AGREES WITH REN REC.) OBT

20" NOW 26" DIA. D.I.F.I.R WITH A FULLY HEALED
DOUBLE BLAZE, BEARS S 53 1/2° E 70.6 FT
(REC. S 52° E, 68.6 FT (1970 DCSO))

