

GOVERNMENT CORNER RESTORATION FORM

Date: 12-23-97 By: JC


This survey consists of:

Township 25S Range 4W Sec. 2 County DOUGLAS Map: _____

State OR Date 12-22-97 No. _____ Narrative: _____

Corner Rpt: CS 64/78-37

Corner Designation



PI # 500600

Previous Renewals 1944 BBI, 1957 BLM, 1973 DC50,

Monument(s) Found: (Condition and Source)

STONE MEASURING 6" x 6"
ON TOP FIRMLY SET 14"
BELOW GROUND WITH A
" + " ON TOP. (1944)

1957 BLM BRASS CAP PIN
A IRON PIPE 6" BELOW
GROUND (1957)

BLM BC/IP BEARS S 20W
1.3 FT FROM CORNER STONE

Accessories Found:

SEE RENEWAL RECORDS PI # 500600

NOTE: 1944 SW RT'S DISTANCE THAT
IS SHOWN ON RENEWAL RECORDS AS BEING
189.8 FT IS AN ERROR & SHAMP WRITTEN
NOTES (CS 53/68) HAS DISTANCE AS 198.8

DOUGLAS COUNTY
SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

SEE PI # 500600

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

NONE

N/A

New Accessories

NONE

Sketch of Monument, Accessories, and General Area

N/A

Location & Comments

NOTE: TWO RAIL ROAD SPIKES PLACE ON TOP OF STONE FOR METAL DETECTABILITY WHEN COVERED UP.

Comp. Declin. 17 3/4 ° E
Agency DCSO
Party Chief RANDALL W. SMITH
Notekeeper [Signature]
Witnesses STEPHEN J. FLAKE

Address

REGISTERED Surveyor
PROFESSIONAL
LAND SURVEYOR

Seal

Randall W. Smith
DALES 6-30-98

OREGON
JULY 25, 1990
RANDALL W. SMITH
2489