

GOVERNMENT CORNER RESTORATION FORM

Date: 1-5-98 By: [Signature]

Township 25S Range 4W Sec. _____

County DOUGLAS This survey consists of:

State OR Date 12-18-97 No. _____

Map: _____

Narrative: _____

Corner Rpt: 64/78-41

Corner Designation

DLC
49

DOUGLAS COUNTY

Condition: SURVEYED Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1930 + 1965 DCSO

Monument(s) Found: (Condition and Source)

7 1/2" DIA BRASS CAPON A
1 1/2" O.D. IRON PIPE PROTRUDING
8" ABOVE GROUND (1965)
3/4" I.D. IRON PIPE PROTRUDING
6" ABOVE GROUND IS ALONG
NORTHERLY EDGE OF BC/IP
(SOURCE UNKNOWN).

COUNTY SURVEYORS OFFICE

T 25S

S, E, D, L, C.

49

R 4 W

1965

Accessories Found:

NO OBTS FOUND

15" NOW BADLY ROTTED CEDAR STUMP, NO BLAZES
OR SCRIBING / VISIBLE, BEARS N74 1/2° W 37.0 FT
(AGREES WITH REC.) 1930

NE BT FROM 1930 IS GONE

NW BT FROM 1965 IS GONE

6" NOW 20" DIA. D. FIR WITH A FULLY HEALED DOUBLE
BLAZE, BEARS N 40° W, 35.8 FT (AGREES
WITH REC.) 1965

