

GOVERNMENT CORNER RESTORATION FORM

Date: 1-15-98 By: JC

Township 25S Range 4W Sec. 11

County DOUGLAS This survey consists of:

State OR Date 1-13-98 No. _____

Map: _____
Narrative: _____
Corner Rpt: 64/79-3

Corner Designation

$\frac{1}{4} \frac{S11}{S14}$

- DOUGLAS COUNTY
 Condition: Surveyor Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals 1929 DCSO + 1957 BLM

Monument(s) Found: (Condition and Source)

3/4" DIA. BRASS CAP ON A 2 1/2" OLD IRON PIPE, PROTRUDES 8" ABOVE GROUND (1957)

1" DIA AXLE PROTRUDES 2" ABOVE GROUND (1929) IS FOUND ALONG NORTH EDGE OF R/1P

U.S. CADASTRAL SURVEY
T25S R4W

S11
 $\frac{1}{4} \frac{S11}{S14}$

1957

BUREAU OF LAND MANAGEMENT

Accessories Found:

21" NOW ROOTED TO GROUND D. FIR, BEARS S 29 1/2° W, 78.6 FT (AGREES WITH REC.) 1957

10" NOW 13" DIA ASH WITH A PARTIALLY HEALED SINGLE BLAZE SCRIBING VISIBLE, "1/4 S11 BT", BEARS N51° W, 9.2 FT (AGREES WITH REC.) 1957

1929 SK BT NOW GONE

14" NOW 23" DIA W. OAK WITH A FULLY HEALED DOUBLE BLAZE, BEARS N 33° W, 46.7 FT (REC N 92° W, 48.9 FT) 1929

10" NOW ROTTED ASH STUMP NO MARKS VISIBLE BEARS N 92° W, 9.2 FT (AGREES WITH REC) 0BT

