

GOVERNMENT CORNER RESTORATION FORM

Date: 1-26-98 By: JC

This survey consists of:

Township 25S Range 4W Sec. 16

County DOUGLAS Map:

State OR

Date 1-21-98

No. \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 64/79-8

Corner Designation

1/4 S 16 / S 21

DOUGLAS COUNTY

SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals 1957 BLM, 1965 DCSO, 95 BLM?

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

3 1/4" DIA. BLM BRASS CAP ON  
A 2 1/2" O.D. IRON PIPE, FLUSH  
WITH GROUND (1957)

U.S. DEPARTMENT OF THE INTERIOR  
T25S R4W

1/4 S 16 / S 21

1957

B. BUREAU OF LAND MANAGEMENT

Accessories Found:

2" NOW 10" DIA. D.F. FIR W/ OAK WITH A FULLY HEALED  
SINGLE BLAZE, BEARS ~~SOME~~ ~~2-98~~ S 70 1/2° E, 29.8  
(AGREES WITH RECF) 1965

6" NOW 10" DIA 2 FT HIGH D.F. FIR STUMP WITH  
SCRIBING VISIBLE "BT" BEARS N 53° W, 59.8 FT  
(AGREES WITH RECF) 1965

UNRECORDED RENEWAL

2" D.F. FIR WITH AN UNHEALED SINGLE BLAZE  
BEARS ~~N 20 3/4° W~~, N 20 3/4° E, 64.7 FT (AGREES  
WITH 6-95 BLM BT TAG)

69-  
BS  
6/95  
N 20 3/4° E

340400  
✓ C

C.S. File No. 64/79-8

