

GOVERNMENT CORNER RESTORATION FORM

Date: 2/24/1998 By: JC

This survey consists of:

Township 24S Range 7W Sec. 31 County DOUGLAS

Map: \_\_\_\_\_

State OR Date 2-18-98 No. \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 64/79-33

Corner Designation

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

$\frac{1}{4} \frac{531}{56}$

MONUMENT DETAIL

Previous Renewals 1960 DCSO

Monument(s) Found: (Condition and Source)

2 1/2" DIA BESS CAP ON 1/2"  
O.D. IRON PIPE PROTRUDES  
2" ABOVE GROUND. (1960)

COUNTY SURVEYORS OFFICE  
T 245 R 7W

$\frac{1}{4} \frac{531}{56}$

T 255 R 7W  
1960

Accessories Found:

18" NOW 26" DIA. B. OAK WITH A PREVIOUSLY OPENED  
UNHEALED ROTTED BLAZE, BEARS N10°W, 12.5 FT  
(AGREES WITH REC.) CRT

5" NOW 20" DIA D.FIR WITH A FULLY HEALED  
DOUBLE BLAZE BEARS N70°E, 9.0 FT  
(AGREES WITH REC.) 1960

6" NOW 6" DIA DOWN D.FIR WITH A ROTTED  
BLAZE ROOT HOLE NEAR RECORD, "S34°E, 9.4 FT 1960

16" D.FIR WITH A FULLY HEALED SINGLE BLAZE  
BEARS S29°W, 14.5 FT (AGREES WITH ROSENBERG  
LUMBER BT TAG DATED 9-8-87 BY F. WHITE)  
THIS BT NOT OF RECORD.

140100.089 ✓  
140700.014 ✓  
C

