

FILED

Date: 10-17-96 By: J.

This survey consists of:

Map: M125-66

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/8-8

OREGON CORNER RESTORATION FORM

Section 34 Township 21S Range 5W

County Douglas Date Oct. 1, 1996

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

NW Corner  
Estes D.L.C. No. 37

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Art Evans, L.S., Deputy County Surveyor, 1951 (CS 44/B7)  
(RM 11-1)

Monument(s) & Accessories Found: (Condition and Source)

Found 12" x 12" x 8" Corner Rock with marks "37"  
on West Side of Rock, and from which rock a:  
4 1/2" Cedar BT, face overgrown, bears N74°E (record  
N45°E), 12 1/2 Feet.  
20" Cedar BT, face overgrown, bears S83°E (record  
N80°E), 37 1/2 Feet (record 37 1/2 feet).  
Rock corner is located at Fence Corner; Fence runs N-S  
and E-W.

Monument Detail

Sketch

(Rock)

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Compass Declination 20°E  
 Firm/Agency Shaner  
Engineering, Inc.  
 Address P.O. Box 1430  
Roseburg, Oregon 97470  
 Party Chief B. Shaner  
 Notes B. Shaner  
 Witness Clem Berlier

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Bruce A Shaner

OREGON  
OCT. 4, 1957  
BRUCE A. SHANER  
430

Renews June 30,  
1998

C.S. File No. 65/8-8