

GOVERNMENT CORNER RESTORATION FORM

Date: 11-13-96 By: AP

This survey consists of:

Township 31S Range 6W Sec. 2 County DOUGLAS

Map: _____

State OR Date 9-25-96

Narrative: _____

No. _____

Corner Rpt: C.S. 65/9-17

Corner Designation

DOUGLAS COUNTY SURVEYOR

S3 | S2
S10 | S11

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

MONUMENT DETAIL

PI# 500600

Previous Renewals 1950 MARKHAM, 1966 DCSG

Monument(s) Found: (Condition and Source)
2 1/2" DIA BRASS CAP ON A 1 1/2" O.D. IRON PIPE PROTRUDES 14" ABOVE GROUND (1966)

1" INSIDE DIA. IRON PIPE PROTRUDES 8" ABOVE GROUND IS FOUND ALONG NORTH SIDE OF RC/IP (SOURCE UNKNOWN)

COUNTY SURVEYORS OFFICE

T31S R6W

S3 | S2
S10 | S11

1966

Accessories Found:

6" NOW 21" DIA. ALMOST DEAD MADRONE WITH A PREVIOUSLY OPENED BLAZE, NO SCRIBING VISIBLE, BEARS N60°E, 42.5 FT. (AGREES WITH REC.) OBT

20" NOW 33" DIA. DEAD MADRONE WITH A PREVIOUSLY OPENED BLAZE, NO SCRIBING VISIBLE, BEARS S80°E, 45.3 FT (REC' S80°E 46.5 FT PER RENEWALS) OBT
NO OTHER OBT'S FOUND

7" NOW 18" DIA DOWN D.FIR WITH A FULLY HEALED DOUBLE BLAZE, BEARS N54°E, 13.5 FT TO ROOT HOLE (AGREES WITH REC.) 1966

16" NOW 18" DIA 5 FT HIGH D.FIR STUMP WITH A FULLY HEALED DOUBLE BLAZE, BEARS S55°E, 12.6 FT (AGREES WITH REC.) 1966

7" NOW 12" DIA 3 FT HIGH D.FIR STUMP WITH A FULLY HEALED DOUBLE BLAZE, BEARS S45°W, 23.0 FT (AGREES WITH REC.) 1966

9" NOW 22" DIA 4.5 FT HIGH D.FIR SNAG WITH A FULLY HEALED DOUBLE BLAZE, BEARS N34°W, 26.6 FT (AGREES WITH REC.) 1966

C.S. File No. 65/9-17

