

GOVERNMENT CORNER RESTORATION FORM

Date: 11-15-96 By: JP

Township 24S Range 1W Sec. 24 County DOUGLAS

This survey consists of:

State OR Date 10-24-96 No. _____

Map: _____
Narrative: _____
Corner Rpt: C.S. 65/9-22

Corner Designation

S 24
1/4 S 25

DOUGLAS COUNTY
Condition SURVEYED Only

- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals # 44

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON 1 1/2"
O. D. IRON PIPE, PROTRUDES
12" ABOVE GROUND (#44)

COUNTY SURVEYORS OFFICE

T 24S

1/4 S 24
S 25

R1W

1965

NOTE: BC IS ORIENTATED
NORTHWESTERLY

Accessories Found:

18" NW 24" DIA HEMLOCK WITH A PARTIALLY HEALED
PREVIOUSLY OPENED BLAZE BEARS S 85° E 4.0 FT
REC S 72° E 3.3 FT BRG HIT'S CENTER OF TRUNK,
DIST WOULD FIT A FACE MEASUREMENT) 0BT

20" NW DOWN AND KOTTED O.F.R. ROOT HOLE
NEAR REC BRG AND DIST " N 90° E 17.8 FT " 0BT

10" NW 12" DIA HEMLOCK WITH A PARTIALLY HEALED
DOUBLE BLAZE, ILLEGIBLE SCRIBING VISIBLE,
BEARS N 22° E 59.4 FT (AGREES WITH REC) #44

