

GOVERNMENT CORNER RESTORATION FORM

Date: 11-19-96 By: JP

Township 29S Range 9W Sec. 21

County DOUGLAS This survey consists of:

State OR Date 10-22-96

No. _____

Map: _____

Narrative: _____

Corner Designation

Corner Rpt: C.S. 65/9-29

1/4 S21 | S22

DOUGLAS COUNTY
SURVEYOR

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals 1978 BLM, 1996 J. MINOR

Monument(s) Found: (Condition and Source)

3 1/4" BLM BRASS CAP ON A
2 1/2" O.D. IRON PIPE PROTRUDING
5" ABOVE GROUND (1978 BLM)

A PROBE OF AREA AROUND
BC/IP WAS MADE A STONE
WAS FOUND ALONG WEST
EDGE OF BC/IP APPROX
4" BELOW GROUND STONE
WAS NOT DUG OUT CORIG
STONE (?)

US DEPT. OF THE INTERIOR

T29S R9W

1/4

S21 | S22

1978

BUR. OF LAND MANAGEMENT

Accessories Found:

9" NOW 9" DIA. D.FIR WITH A FULLY HEALED
BLAZE BEARS N38W, 10.5 FT TO
CENTER OF ROOT CROWN (AGREES WITH 1978 BLM REC)

REC PER 1996 J. MINOR N44W, 10.5 FT
WELL WITH CENTER OF TRUNK NOTE: BT IS A
PISTOL BUTT

NO OTHER BT'S FOUND

