

GOVERNMENT CORNER RESTORATION FORM

Date: 11-19-96 By: JP

Township 30 S Range 8 W Sec. 21 County DOUGLAS

This survey consists of:

State OR Date 10-23-96 No. \_\_\_\_\_

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: C.S. 65/9-31

Corner Designation

S21 | S22  
S28 | S27

DOUGLAS COUNTY

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals #57, #139, 1975 BLM

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON A 1 1/2" O.D. IRON PIPE PROTRUDES 8" ABOVE GROUND. (#57)

COUNTY SURVEYORS OFFICE

T 30 S

S21 | S22

S28 | S27

R 8 W

1965

Accessories Found:

- 8" NOW 22" DIA D.FIR WITH A FULLY HEALED DOUBLE BLAZE, BEARS S25°W, 19.0 FT (REC. S25°W, 18.5 DIST WOULD GO TO ORIG. FACE.) OBT
- 8" NOW 10" DIA 1 FT HIGH ROTTED D.FIR STUMP NO SCRIBING VISIBLE BEARS N33°E 7.9 FT TO CENTER (REC. N33°E 7.2 FT) OBT
- 14" NOW 33" DIA. TIPPED OUT OF GROUND D.FIR NO SCRIBING VISIBLE ROOT HOLE AGREES WELL WITH REC " N 71°W, 11.9 FT. OBT
- 16" NOW 18" DIA TIPPED OUT OF POSITION D.FIR STUMP WITH A PARTIALLY HEALED BLAZE, ILLEGIBLE SCRIBING VISIBLE, ROOT HOLE NEAR REC. BRG AND DIST. " N 26°E 16.6 FT" #57
- 8" NOW 9" DIA TIPPED OUT OF POSITION AND ROTTED CEDAR ROOT HOLE NEAR REC. BRG. AND DIST. " S13°E, 35.6 FT" #57
- 10" NOW 10" DIA. TIPPED OUT OF POSITION D.FIR STUMP SOIL COVERED NO ROOT HOLE REC BRG + DIST " S 82 1/2°E 37.3 FT" 1975 BLM
- 30" NOW 30" DIA TIPPED OUT OF POSITION D.FIR WITH AN UNHEALED BLAZE SCRIBING VISIBLE "T30S R8W S21 BT" ROOT HOLE NEAR REC BRG AND DIST. " N 36 1/2°W 30.4 FT" 1975 BLM

CS. File No. 65/9-31

