

FILED

M 124-63

Date: 10/20/97 By: JP

This survey consists of:

Map: M 124-63

Narrative:

Corner Rpt: CS 65/15-17

OREGON CORNER RESTORATION FORM

Section 26 Township 26S Range 5W

County Douglas Date October 20, 1997

DOUGLAS COUNTY SURVEYOR

Corner Designation

SE Corner
Hiram Dixon D.L.C. No. 41

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Douglas County Surveyor, CS 49/125, March, 1972

Monument(s) & Accessories Found: (Condition and Source)

Found 5/8" Iron Rod on E Sunshine Road (Set PK over)
(strong mag. on metal detector), from which a:

16" W. DAK BT bears N25°W, 69.2 feet (Face over/grown)

5/8" Iron Rod bears S10°W, 29.1 feet (IN E-W fence line)

Monument Detail

Sketch

None.

Monument Set (Procedures and Description)

(Set PK over.)

New Accessories

None. (However, survey done for Don Collins ties this.)

Location & Comments

County Surveyor
may wish to
re-monument
this important
corner.

Compass Declination 20°E
 Firm/Agency Shaner
 Engineering, Inc
 Address P.O. Box 1430
 Roseburg
 Party Chief B. Shaner
 Notes " "
 Witness D. Snyder

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Bruce A Shaner

OREGON OCT. 4, 1967 BRUCE A. SHANER 490

Renews June 30, '98

C.S. File No. 65/15-17