

FILED

Date: 1-21-98 By: JP

This survey consists of:

Map: _____

Narrative: _____

Corrler Rpt: C565/20-2

**CORNER RESTORATION
IN
SECTION 23, T. 26 S., R. 8 W., W.M.
DOUGLAS COUNTY, OREGON
MAY, 1997**

**DOUGLAS COUNTY
SURVEYOR**

In order to preserve the location of the S ¼ Corner of Section 23, T. 26 S., R. 8 W., W.M. two new bearing trees were marked as follows:

28" Cedar, scribed " S 23 ¼ BT "
Bears: N 67° E, 79.0 feet

12" Yew, scribed " S 26 ¼ BT "
Bears: S 16°30' E, 103.1 feet

Distances are to 6" spikes place below scribed faces.

The corner which was set by R.C. ADAMEK in 1975, falls in a draw which is covered by road fill. During winter storms a portion of the fill washed out exposing one of ADAMEK'S BT'S. The corner position was determined by magnetic bearing and distance from the " W " nail in the root collar of the BT which was listed on both the plat and tag as N 31° E, 10.0 feet (Corner to tag). The stump, (48" FIR), tag, and " W " nail are all in good condition but will be covered by fill once the road is repaired.

In the event that ADAMEK'S Basis of Bearing is obtained by survey, the corner position may be more accurately determined using the following distances which are from the " W " nail in the 48" stump to the spikes in the new BT'S.

113.1 feet to 12" Yew
71.4 feet to 28" Cedar

There is also a " W " nail in a 24" fir stump which is S 07° W, 81.9 feet from the calculated corner position. Another fir stump which has a WEYERHAEUSER tag is sliding into the road and will probably be removed during road repairs.

All measurements were taken with a Nikon DTM-720 Total Station.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Tony Hostetter
**OREGON
JAN. 19, 1982
TONY HOSTETTER
1975**

C.S. File No. 65/20-2