

FILED

Date: 11-30-1999 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/23-20

OREGON CORNER RESTORATION FORM

Section 1E12 Township 26S Range 07W

County Douglas Date 10/25/99

DOUGLAS COUNTY
SURVEYOR

Corner Designation

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

No. 1/4 Corner, Sec. 12 - BC on pipe at base of Oak in good condition
14" W. Fir BT now 21" Stump Brg. N52W, 22.5' reattach BT Tag
11" Oak now 12" W. Oak Brg. S35W, 66.3' has visible scar and tag
14" Oak now 18" B. Oak Brg. South, 1.5' has visible scar and tag (tag not filled out)

Monument Detail

Sketch

* No trace of orig. 1855 BT's

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 19.5°
 Firm/Agency Sweeden Land Surveying
 Address 5211 Cole Rd Oakland OR. 97462
 Party Chief C. Sweeden
 Notes C. Sweeden
 Witness E. Wilds



Exp. 6/30/00

C.S. File No. 65/23-20