

Corner No. 4

OREGON CORNER RESTORATION FORM

Section 34 Township 32S Range TW

County Douglas Date March, 2002

Corner Designation

N - N 1/64
533 • 534

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Corner set by RLS Templin, Map No. M 122-53, in 1995.

Monument(s) & Accessories Found: (Condition and Source)

Found 5/8" Iron Rod with yellow plastic cap marked "Templin LS 2359" from which a:
12" Tan Oak BT, scribes visible, bears 527°E, 31 1/2 feet. Scribed "1/64 534 BT".
8" D. Fir BT, face overgrown, bears 574°E, 17 1/2 feet.

(These BT's were not of record.)

Monument Detail

Sketch

FILED

Date: 3/27/2002 By: JK

This survey consists of:

Map: M 137-35

Narrative:

Corner Rpt: 65/42-11 thru 39

DOUGLAS COUNTY SURVEYOR

Monument Set (Procedures and Description)

N/A

New Accessories

6 Foot Steel Fence Post bears North, 10 feet.
" " " " " " West, 10 feet.

Location & Comments

Surveyor's Seal

Compass Declination 20°E

Firm/Agency Shaner

ENGINEERING

Address PO Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Paul Schneider

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner
 OREGON
 OCT. 4, 1957
 BRUCE A. SHANER
 430

Renewed June 30,

C.S. File No. 65/42-14 2002