

OREGON CORNER RESTORATION FORM

Corner No. 7

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Corner Designation

N 1/16
528 ϕ 527

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Corner was set by BLS Price, Map No. CS 42/142, in 1956.

Monument(s) & Accessories Found: (Condition and Source)

Found a 1" Iron Pipe, from which a:
20" D. Fir BT, face overgrown, bears N8°E,
193 feet,
36" Sugar Pine BT, " " , bears S56°W,
300 feet.

(above trees not of record)

Monument Detail

Sketch

FILED

Date: 3/27/2002 By: JL

This survey consists of:

Map: M137-35

Narrative: _____

Corner Rpt: 65/42-11 thru 39

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

N/A

New Accessories

Set a 6 foot steel fence post, North, 10 foot.

Location & Comments

Surveyor's Seal

Compass Declination 20E

Firm/Agency Shaner

Engineering

Address P.O. Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Bob Schneider

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner
OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Renews June 30,

C.S. File No. 65/42-17 2002