

OREGON CORNER RESTORATION FORM

Corner No. 8

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Corner Designation

521/522
528/527

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals/Surveys, etc.

RLS Price renewed corner, C.S. File No. 41/373, in 1955.

Monument(s) & Accessories Found: (Condition and Source)

Found 2" Iron Pipe, from which a:
36" D. Fir BT, bark scribes visible, bears N30°E
(Record N25°E), 22⁴ feet.
34" D. Fir BT, bark scribes visible, bears S62°W,
19⁸ feet.
20" Madrone BT, face overgrown, bears N50°W,
26² feet (record 28⁴ = slope distance).

Monument Detail

Sketch

FILED

Date: 3/27/2002 By: JC
This survey consists of:
Map: M137-35
Narrative:
Corner Rpt: 65/42-11 thru 39

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

N/A

New Accessories

10" Madrone BT, I scribed "T32S, R7W, 527, BT" on bark,
bears S15°E, 16⁰ feet.
6 Foot steel fence post bears South, 1⁰ feet.

Location & Comments

Surveyor's Seal

Compass Declination 20°E
Firm/Agency Shaner
Engineering
Address PO. Box 1430
Roseburg, OR 97470
Party Chief B. Shaner
Notes " "
Witness Paul Schneider

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner

OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Renews June 30,
C.S. File No 65/42-18 2002