

OREGON CORNER RESTORATION FORM

Corner No. 9

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Corner Designation

$\frac{1}{4}$   $\frac{S22}{S27}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

RLS Price renewed Corner, C.S. File 41/373, in 1955.

Monument(s) & Accessories Found: (Condition and Source)

Found 1 1/2" Iron Pipe in mound of stone, from which a:  
20" Madrone, original BT, face overgrown, bears N18°E,  
54 1/2 feet.

32" D. Fir, original BT, now snag, face overgrown,  
bears S75°E, 29 1/2 feet. *(scribes visible)*

14" Cedar BT, face overgrown, bears N86°E, 43 1/2 feet.

36" Cedar BT, scribes visible (now snag), bears South,  
35 1/2 feet.

Monument Detail

Sketch

FILED

Date: 3/27/2002 By: X

This survey consists of:

Map: M137-35

Narrative:

Corner Rpt: 65/42-11 thru 39

DOUGLAS COUNTY  
SURVEYOR

Monument Set (Procedures and Description)

N/A

New Accessories

None.

Location & Comments

Corner sets in  
rocky opening.

Compass Declination 20°E

Firm/Agency Shaner  
Engineering

Address P.O. Box 1430  
Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Ron Schneider

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Bruce A. Shaner

OREGON  
OCT. 4, 1957  
BRUCE A. SHANER  
430

C.S. File No. 65/42-19 Renews June 30,  
2002