


OREGON CORNER RESTORATION FORM

CORNER No. 25

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Mining claim
Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Briggs, U.S.G.L.O., 1901 Survey Plat.

RLS Van Swearingen, Map No. M21-61, 1961 Survey.

Monument(s) & Accessories Found: (Condition and Source)

Found Drill Steel in mound of stone, from which a:
10" Madrone BT, now snag, face rotted out, bears N18°E (record
N26°E), 150 feet. (Shows tag & axe marks.)

Monument Detail

Sketch

FILED

Date: 3/27/2002 By: X

This survey consists of:

Map: M137-35

Narrative: _____

Corner Rpt: 65/42-35

**DOUGLAS COUNTY
SURVEYOR**

Monument Set (Procedures and Description)

New Accessories

18" D. Fir BT, I scribed "MCBT" bears N1°W, 100 feet.
14" D. Fir BT, I scribed "MCBT" bears N65°E, 16 1/2 feet.

6 Foot Steel Fence Post bears South, 0 1/2 feet.

Location & Comments

Compass Declination 20°E
 Firm/Agency Shaner Engineering
 Address P.O. Box 1430
Roseburg, OR 97470
 Party Chief B. Shaner
 Notes " "
 Witness Ken Schneider

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner

OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Renews June 30,

2002

C.S. File No 65/42-35