


OREGON CORNER RESTORATION FORM

CORNER No. 27

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Mining Claim
Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Briggs, U.S.G.L.O., 1901 Survey Plat.

RLS Van Swearingen, Map No. 21-61, 1961 Survey.

Monument(s) & Accessories Found: (Condition and Source)

Found 1" Iron Pipe in mound of stone, from which a:

26" D. Fir, original BT, face overgrown, bears S52°W, 37.7 feet.

28" Pine, original BT, scribes visible, bears N24°E,

43.0 feet (record 42 feet).

Monument Detail

Sketch

FILED

Date: 3/27/2002 By: JK

This survey consists of:

Map: M137-35

Narrative: _____

Corner Rot: 65/42-11 thru 39

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

6 Foot Steel Fence Post bears S30°W, 12 foot

Location & Comments

Surveyor's Seal

Compass Declination 20°E

Firm/Agency Shaner

Engineering

Address P.O. Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Ben Schneider

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A Shaner

OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

C.S. File No 65/42-37 Renews June 30, 2002