

FILED

Date: 8/27/2003 By: JP

This survey consists of:

RE: Map: M116-65

Narrative: _____

Corner Rpt: _____

DOUGLAS COUNTY
SURVEYOR

BISHOP SURVEYING, INC.

87830 Terrace View Drive

Florence, Or. 97439

Aug. 20, 2003

Douglas County Surveyor
Courthouse Room 105-A
Roseburg, Or. 97470

Re: Map File M116-65

Dear Mr. Ware:

On Aug. 20, 2003 in the company of Mr. Fred Gidney, the recent purchaser of Lots 9 & 10 as shown on the above referenced map, and after recovering and having tied the other three corners we dug a hole about 2 feet deep at the record position of the Northeast corner of Lot 10. which according to the neighbors could be buried by as much as 5 feet by a slide in 1996. My metal detector indicates that there is ferrous metal at that location but due to large rocks in this slide and the demonstrated reliability of the record per M116-65 abandoned the excavation and set a 5/8 " X 30" Iron Rod with a red plastic cap marked "LS 896" at record bearing and distance from the found Northwest monument.

Please enter this into the survey records as per your phone message this A.M.

Thanks

Larry D. Bishop PLS 896

C.S. File No 65/46-7