

**Township 21 South, Range 8 West
Section 32**

N ¼ Corner Section 32: Found 1945 Brass Cap on Iron Pipe firmly set. We Set a 6 foot galvanized steel fence post alongside with top painted red.

Old Bearing Trees Taken in 1945 by GLO:

28" D. Fir Stump (record Hemlock), N 53° W (record N 43 ½° W), 15 links, with visible scribes and old bearing tree tag.

18" rotted D. Fir Stump (record Hemlock), S 4° E (record S 11 ½° E), 79 links, with no visible scribe and old bearing tree tag.

New Bearing Trees Taken this Survey:

17" D. Fir, West, 8.2 feet to spike set side center, scribed "T21R81/4S29BT" with aluminum tag

19" D. Fir, S 12° E, 20.1 feet to spike set side center, scribed "T21R81/4S32BT" with aluminum tag

15" D. Fir, N 86° E, 17.3 feet to spike set side center, scribed "T21R81/4S29BT" with aluminum tag

17" D. Fir, N 11° E, 15.5 feet to spike set side center, scribed "T21R81/4S29BT" with aluminum tag



Expires 6/04

FILED
Date: 3/8/2004 By: X
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 65/49-20
DOUGLAS COUNTY
SURVEYOR

240200 Rec'd Feb 2004

C.S. File No 65/49-20