

**Township 21 South, Range 8 West
Section 32**

E ¼ Corner Section 32: Found 1945 Brass Cap on Iron Pipe firmly set. We Set a 6 foot galvanized steel fence post alongside with top painted red.

Old Bearing Trees Taken in 1945 by GLO:

30" rotted D. Fir, N 40 ½ ° W, 171 links, no marks, no tag.

The other record tree is gone.

New Bearing Trees Taken this Survey:

9" D. Fir, N 71° W, 5.8 feet to spike set side center, scribed "T21R81/4S32BT" with aluminum tag

13" D. Fir, S 49° W, 16.7 feet to spike set side center, scribed "T21R81/4S32BT" with aluminum tag

13" D. Fir, S 70° E, 33.5 feet to spike set side center, scribed "T21R81/4S33BT" with aluminum tag

16" D. Fir, N 50° E, 13.6 feet to spike set side center, scribed "T21R81/4S33BT" with aluminum tag

FILED
Date: 3/8/2004 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 65/49-22

DOUGLAS COUNTY
SURVEYOR

