

**FIRST RE-ESTABLISHMENT**  
GCDB 340400

Quarter corner common to Sections 16 and 21, Township 32 South, Range 1 West, W.M.

Fd. the single remaining original bearing tree, a Douglas Fir, 39 ins. diam., containing scribed "BT" in opened lower face, as recorded by R.S. Moore, in 1883. From the proceeding original evidence, set a 1x36 ins. galvanized iron pipe, 27 ins. in the ground with a 2½ ins. diam. brass cap mkd:

T32S R1W  
16  
¼S—  
21  
C.S.  
1987

from which, the above described original bearing tree brs. record; S25°W, 6.6 ft. to scribed face.  
Remeasured 6.93 ft. to center of tree at lower blaze.

Mkd. new tree "CS" "BT":

Douglas Fir, 9 ins. diam., brs. N31°W, 25.05 ft. to center of tree at lower blaze.  
Corner lies on 50% East slope and about 140 ft. East of a spur that slopes S30°E.

February 12, 1987  
T.Newcomb  
R.Romio

Edward McGinty  
County Surveyor

**FILED**

Date: 8-13-05 By: JC

V=20°

This survey consists of:

p-46

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 65/54-36

**DOUGLAS COUNTY  
SURVEYOR**

*Leonard,*

*I read your corner report for T32S, R1W for sec. cor. 16, 17, 20 & 21, and noticed there was no mention of the ¼ cor. of 16 & 21.*

*I thought maybe we neglected to file it with the Douglas County Surveyors Office. There has been no survey tie to this corner.*

*Thomas Newcomb  
Jackson County Surveyors Office  
8/23/05*

C.S. File No 65/54-36