

CORNER REPORT FORM

Section 2 Township 30S Range 3W

Douglas County Date 2-2012

CORNER DESIGNATION

500640

Condition Report only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced out

Previous Renewals/Surveys, etc:

DCSO 1960 - 1967

M 86-6 M 1751

Monument(s) & Accessories Found: (Condition and Source)

DCSO BRASS CAP

40" FIR Stump S22 1/2 E 20.3 FT Prvw. opened  
12" CHINGUAPIN S18W 4.3 FT DOWN & ROTTEN FACE DISABLE  
20" DFIR N41 E 20.9 FT GOOD SCAR  
22" DFIR N51W 17.4 FT GOOD SCAR

Monument Detail

Sketch

DOUGLAS COUNTY SURVEYORS OFFICE  
BRASS CAP 12" ABOVE GROUND

FILED

Date: 2/24/2012 By: JC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 25/76-20

DOUGLAS COUNTY  
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

10" D. FIR S38W 32.0 FT scribed 1/4 53 RT  
ON SINGLE FACE

A 6" D. FIR S27E 18.1 FT scribed 1/4 52 RT  
ON SINGLE FACE

Location & Comments

CORNER IS ON  
A EAST FACING  
Hillside approx  
650 south of C.R.  
CORNER 212

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 S.E. Pine Street  
Roseburg, OR 97470

Party Chief: Ron Quimby

Notes:

Witness:

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 14, 1978  
RONALD A. QIMBY  
1654

EXP 12-31-12

C.S. File No 65/76-20