

CORNER REPORT FORM

Section 2 Township 30S Range 3W
Douglas County Date 2-12

CORNER DESIGNATION

500700

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

DCSO 1960
M 86-6 M 145-76 M 17-51

Monument(s) & Accessories Found: (Condition and Source)

DCSO BRASS CAP
30" MADRONA S40°E 21.6 FT Rotted FACE
41" D. FIR (~~STAG~~ SNA9) N15³/₄E 41.9 FT Healed FACE
A CAPPED 46" D FIR STUMP S30W 11.6 FT Healed FACE

Monument Detail

Sketch

DOUGLAS COUNTY SURVEYOR OFFICE
BRASS CAP 14" ABOVE GROUND

FILED
Date: 2/24/2012 By: X
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/76-21

Monument Set (Procedures and Description)

DOUGLAS COUNTY
SURVEYOR

New Accessories

A 8" D. FIR BEARS S66°E 9³/₄ FT scribed CC S2 BT
ON SINGLE FACE
A 6" D. FIR BEARS S88W 5¹/₂ FT scribed CC S3 BT
ON SINGLE FACE

Location & Comments

Surveyor's Seal

CORNER IS ON THE
E-W BOUNDARY OF
A CLEAR CUT UNIT TO
TO THE NORTH APPROX
300' SOUTH OF ROAD
JUST WEST OF THE
TOP OF A N-S RIDGE

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 S.E. Pine Street
Roseburg, OR 97470

Party Chief: R. Quimby

Notes:

Witness:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-12

C.S. File No 65/76-21