

CORNER REPORT FORM

Section 2 Township T305 Range 3W
Douglas County Date 2/2012

CORNER DESIGNATION

540900

Condition Report only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced out

Previous Renewals/Surveys, etc:

M 17-51
M 86-6

Monument(s) & Accessories Found: (Condition and Source)

Fd 5/8" BRASS ROD
BT'S Per M 86-6 Now Rotted stumps

Monument Detail

Sketch

Fd 5/8" BRASS ROD 6"
Above GROUND

FILED
Date: 2/24/2012 By: X
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/76-23

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

NONE

New Accessories

12" D FIR S41°W 7° FT scribed 1/4 SZ BT
ON SINGLE FACE
8" D FIR S33°W 3° FT scribed X breast HIGH BT @ BASE
6" D FIR N80°W 7° FT scribed X breast High BT @ BASE
16" D FIR S41°W 17° FT scribed 1/4 SZ BT ON SINGLE FACE

Location & Comments

CORNER IS ON A STEEP
EAST SLOPE APPROX 225'
EAST OF ROAD & APPROX
75' WEST OF S 1/4 COR
OF SEC 35

Compass Declination

Firm/Agency: i.e. Engineering, Inc.

Address: 809 S.E. Pine Street
Roseburg, OR 97470

Party Chief: R. Quimby *[Signature]*

Notes:

Witness:

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXP 12-31-12

C.S. File No 65/76-23