

OREGON CORNER RESTORATION FORM

FILED

Date: 5-2-2012 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/76-53

Section 36 Township 19 South, Range 9 West
County Douglas Date 1 May 2012

DOUGLAS COUNTY
SURVEYOR

Corner Description

CE1/16

Section 36

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals / Surveys, etc.

5/8" Rebar set in 1977 administrative survey by the Coos Bay, BLM office.

No bearing trees were scribed

Monument (s) & Accessories Found: (Condition and Source)

Found - 5/8" Rebar set in 1977 administrative survey by the Coos Bay BLM office.

No accessories in evidence.

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

16" D. Fir bears N 88° E 23.3 ft. blazed, scribed, CE1/16 S36 BT

8" D. Fir bears S 43° E 4.4 ft. blazed, scribed, CE1/16 S36 BT

Location & Comments

Corner has steel post
adjacent to it.

All BT's have red painted
bands and yellow tags.

Compass Declination 16° East

Firm/Agency Northwest Land

Surveying Inc.

Address P.O. Box 2827

Florence, OR 97439

Party Chief Ron Rice

Notes _____

Witness Jason Collver

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
54633LS

RENEWS: 12-31-2012

C.S. File No 65/76-53